

Job Code	Client Name	Job Type	Service Description	Special Instructions	Start Date
5135	Merwin Dela Cruz - J. Epstein	Water Treatment	Cooling Tower - Monthly Maintenance	perform water treatment on Cooling tower Include PSR with water levels and readings	09-Apr-2018
5136	Merwin Dela Cruz - J. Epstein	Tower Cleaning	Cleaning & Disinfection - Cooling Tower		25-Apr-2018
5135.1	Merwin Dela Cruz - J. Epstein	Water Treatment	Cooling Tower - Monthly Maintenance	perform water treatment on Cooling tower Include PSR with water levels and readings	07-May-2018
4849.1	Merwin Dela Cruz - J. Epstein	Legionella Test	Cooling Tower - Legionella	Completion Notes did the 90 day tower inspection and legionella test.	23-May-2018
5135.2	Merwin Dela Cruz - J. Epstein	Water Treatment	Cooling Tower - Monthly Maintenance	perform water treatment on Cooling tower Include PSR with water levels and readings	11-Jun-2018
5135.3	Merwin Dela Cruz - J. Epstein	Water Treatment	Cooling Tower - Monthly Maintenance	perform water treatment on Cooling tower Include PSR with water levels and readings	09-Jul-2018
5135.4	Merwin Dela Cruz - J. Epstein	Water Treatment	Cooling Tower - Monthly Maintenance	perform water treatment on Cooling tower Include PSR with water levels and readings	13-Aug-2018
4849.2	Merwin Dela Cruz - J. Epstein	Legionella Test	Cooling Tower - Legionella	90 day tower inspection and legionella test.	21-Aug-2018
5135.5	Merwin Dela Cruz - J. Epstein	Water Treatment	Cooling Tower - Monthly Maintenance	perform water treatment on Cooling tower Include PSR with water levels and readings	10-Sep-2018
5135.6	Merwin Dela Cruz - J. Epstein	Water Treatment	Cooling Tower - Monthly Maintenance	perform water treatment on Cooling tower Include PSR with water levels and readings	08-Oct-2018
5136.1	Merwin Dela Cruz - J. Epstein	Tower Cleaning	Cleaning & Disinfection - Cooling Tower		15-Oct-2018
5137	Merwin Dela Cruz - J. Epstein	Inspection	Annual Cooling Tower - Inspection		22-Oct-2018
5135.7	Merwin Dela Cruz - J. Epstein	Water Treatment	Cooling Tower - Monthly Maintenance	perform water treatment on Cooling tower Include PSR with water levels and readings	12-Nov-2018
4849.3	Merwin Dela Cruz - J. Epstein	Legionella Test	Cooling Tower - Legionella	90 day tower inspection and legionella test.	19-Nov-2018
5135.8	Merwin Dela Cruz - J. Epstein	Water Treatment	Cooling Tower - Monthly Maintenance	perform water treatment on Cooling tower Include PSR with water levels and readings	10-Dec-2018

0322  
1125